

6223 Thompson Rd. Syracuse, NY 13206
P.O. Box 88 East Syracuse, NY 13057
(315) 463-9500 FAX (315) 463-9290
Facility # 7106946

June 21, 2010

Mr. Stephen Condon
Senior Engineering Geologist
NYS Department of Environmental Conservation
Bureau of Hazardous Waste & Radiation Management, 9th Floor
Division of Solid & Hazardous Materials
625 Broadway
Albany, NY 12233-7258

Re: Former Roth Bros. Smelting Corp. Site
6223 Thompson Road, Dewitt, New York
Consent Order C7-0001-94-10

Annual Asphalt Cap Inspection


Dear Mr. Condon:

On June 16, 2010, Mr. Chris Laurin from Ruston Paving Company, Inc., conducted the annual inspection of the asphalt cap covering the corrective action management unit (CAMU) at the above referenced site. Results of the annual inspection are being submitted to meet the annual inspection reporting requirements. A copy of the 2010 Ruston Paving Report, which includes photographs of the existing CAMU asphalt cap and the repair areas, is attached.

The asphalt cap had some minor areas in need of repair and a few noted areas of vegetation growth along the joint between the concrete dolly apron and the asphalt. Vegetation was also observed growing along the eastern side slope but not directly on the CAMU asphalt cap. The vegetation was treated with a non-selective herbicide (Round-Up) then the entire area was power swept. As done previously, the asphalt repair areas were filled with a hot asphalt mix and the repair edges were sealed.

If you have any questions about the attached inspection report or any of the routine repair work performed, please do not hesitate to contact me.

Sincerely,


Dennis Flanagan
General Manager



Ruston Paving Company, Inc.

6216 Thompson Road • Syracuse, New York 13206

Tel: (315) 437-2533
Fax: (315) 437-1775
www.rustonpaving.com

June 16, 2010

Metalico Aluminum Recovery, Inc.
C/O: Burt Coleman
6223 Thompson Road
Syracuse, New York 13206

Dear Mr. Coleman:

Re. CAMU Cover Repairs

I have completed the inspection of the asphalt cover on the CAMU area. I have found a few minor areas of damage to the asphalt pavement and a few spots of vegetation growing along the joint between the concrete dolly apron and asphalt pavement. Vegetation is also growing along the slope on the east side but has not entered the CAMU cap area.


Repair Procedures:

Fill depressions with hot mix asphalt and crack seal edges.
Treat all vegetation with a non selective herbicide (Round-up).

All repairs were completed by June 16, 2010.

Should you have any questions or concerns, please contact me at (315) 437-2533.

Sincerely,
Ruston Paving Co., Inc.


Chris Lauria
Project Manager

